Report ID: MAXIA20251118023121 Test Time: 2025-11-18 02:31:21

Technician: --

# 2023 Lexus Vehicle Diagnostic Report

## **Vehicle Information**

2023/Lexus/RC350/2GR-FKS VIN: JTHGZ5DC5P5012310

Odometer Reading: 4290km License Plate: NJGGHBN

**Customer Information** 

Name: -- Tel: --

**Device information** 

Scanner: MaxiCheck MX900

Version: V6.80

Serial Number: DR8GS1C01666

Repair Order Number:

DR8GS1C0166620251118023035707

# 🔀 System Scanned ( 41 ) Status/DTC System Engine **0 Transmission** SRS airbag **O** Combination meter **O** Brake/EPB **O** Tire pressure monitor **O** Main body **O** Driver door motor **2** 0 Right mirror **O** Left mirror Sliding roof **O O** Passenger seat **Driver seat O** Passenger door motor **O** Air conditioner **O** Telematics **O** Active sound control(ASC) **O** Blind spot monitor (BSM) slave **O** Blind spot monitor (BSM) master **0** Front radar sensor

MaxiCheck MX900

# Smart access (1 DTC)

DTC	Description	Status
B27A1	Driver side electrical antenna circuit open	Current

### **Technician Notes**

**AUTEL** www.autel.com MaxiCheck MX900 Page 2

2023/Lexus/RC350/2GR-FKS	Test Time: 2025-11-18 02:31:21	Report ID: MAXIA20251118023121

Customer name: _	
Technician: _	
Date: _	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiCheck MX900 Page 3