شهادة الفحص هذه تظهرحالة المركبة وقت الفحص فقط و وتعتبر الشهادة غير سارية بمجرد خروج المركبة This Inspection Certificate is valid and shows the vehicle condition at the time of condition as soon as it leaves the inspection station and from then on, the inspection is considered invalid. Al Mumayaz Vehicle Testing is not responsible المركبة للتسجيل for the hidden defects in the vehicle, according to this Al Mumayaz does not guarantee the vehicle validity for registration.

من حارة الفحص كما لا تضمن المميز لفحص المركبات حالة المركبة بمجرد خروجها من حارة الفحص المميز . athe inspection only. Al Mumayaz Vehicle Testing doesn't guarantee the vehicle لفحص المركبات غير مسؤولة عن العيوب الخفية في المركبة كما لا تضمن بموجب هذه الشهادة صلاحية

Test Date	09-09-2025	تاريخ الفحص	Test Type	COMPREHENSIVE	نوع الفحص
Model	Attrage	نوع	Year	2014	سنة التصنيع
Make	Mitsubishi (Car)	ل/نوع	Vehicle Status	UN-REGISTERED	حالة المركبة
Site Name	Rashidiya Pioneer	اسم الموقع	Tested By		المفحوص بواسطة
Cylinders	3	عدد الاسطوانات	Chassis Number	MMBSTA13AEH012113	رقم الشاسيه
Fuel Type	Petrol	نوع الوقود	<b>Engine Number</b>		رقم المحرك
Mileage	309946	المسافة المقطوعة	Vehicle Color	White	لون المركبة

## **Automatic Test**

Defect	Result	عيب
Brake System	Not Tested	نظام الفرامل
Exhaust Gas Test	Not Tested	اختبار غاز العادم
Shock Absorber Test	Not Tested	اختبار ممتص الصدمات
Carbon-di-oxide Relative		نسبة ثاني أكسيد الكربون
HC Relative		نسبة الهيدروكربونات

<u>Visual Test</u>						
Defect	Remarks	عيب				
Sign of Front Accident		علامة حادث أمامي				
Sign of Rear Accident		علامة حادث خلفي				
A/C Condition	a/c low cooling .	حالة المكيف				
Bumpers	scratches & refitted .	المصدات				
Gear Defect	Gear defect .	عيب في التروس				
Side Safety Frame	Bulk head / fender frame /rad. frame repaired .	الإطار الجانبي للأمان				
Engine Oil Leaking	•	تسريب زيت المحرك				
Sign of Side Accident		علامة حادث جانبي				
Digital Display Damaged / Warning Lights	Engine & warning lights on .	تلف العرض الرقمي / أضواء التحذير				
Body Repainted	Body portions repaired & repainted scratches dent.	إعادة طلاء الهيكل				
Engine Not OK	Engine misfire & starting problem / knocking .	المحرك غير جيد				
Doors	front right & rear both side doors ,bonnet & trunk portions repaired .trunk not closing .	الأبواب				
Others	vehicle has starting problem / while testing vehicle not start .	أخرى				
Fenders	repaired .	الرفارف				
Seats Condition & Seats Fixing	seats & trims torn .	حالة المقاعد وتثبيتها				
Chassis (Frame)	chassis ok .	الشاسيه (الإطار)				

about:blank 1/1